Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1 BRS	L1	9	(chip or processor) same fan same emi	USPAT	2003/07/02 13:18			0
2 BRS	L2	274	(chip or processor) same fan same (heat adj sink)	USPAT	2003/07/02 13:30			0
3 BRS	L3	560	(chip or processor) same (fan same speed)	USPAT	2003/07/02 13:31			0
4 BRS	L4	141	(chip or processor) same cooling same (fan same speed)	USPAT	2003/07/02 13:31			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1 BRS	L1	1	(chip or processos or microprocessor) same (emi same cover) and fan	USPAT	2003/07/0 2 10:37			0
2 BRS	L2	7	(chip or processor or microprocessor) same (emi same cover) and fan	USPAT	2003/07/0 2 10:40			0
3 BRS	L3	1	(chip or processor or microprocessor) same (emi same cover) and fan	USPA; IBM_TDB	2003/07/0 2 10:40			0
4 BRS	L4	75	(chip or processor or microprocessor) and (emi same cover) and fan	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 2 10:53			0
5 BRS	L5	68	4 not 2	USPAT	2003/07/0 2 10:40			0
6 BRS	L6	290	(chip or processor or microprocessor) and (emi same cover)	USPAT	2003/07/0 2 10:50			0
7 BRS	L7	215	6 not 4	USPAT	2003/07/0 2 10:44			0
8 BRS	L8	21	(chip or processor or microprocessor) and (emi same cover)	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 2 10:50			0
9 BRS	L9	1	(chip or processor or microprocessor) and (emi same cover) and fan	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 2 11:00			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
10	IS&R	L10	5	(("6455864") or ("6261508") or ("5889316") or ("5548125") or ("5635754") or ("6261508") or ("6455864")).PN.	USPAT	2003/07/02 10:55			0
11	IS&R	L11	75	(("4273200") or ("4094560") or ("2278740") or ("2237053") or ("62125651") or ("61004250") or ("61004249") or ("60180150") or ("60124834") or ("60106150") or ("57095650") or ("56103452") or ("2584863") or ("60160327") or ("5889316") or ("5888850") or ("5880403") or ("5864088") or ("5851852") or ("5825042") or ("5824568") or ("5780163") or ("5770304") or ("5714102") or ("5672918") or ("5610443") or ("5589129") or ("5577319") or ("5561265") or ("5552338") or ("5527742") or ("5441900") or	USPAT	2003/07/02 10:57			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
12	IS&R	L12	4	(("5530202") or ("5422433") or ("5409949") or ("5355016")).PN.	USPAT	2003/07/0 10:58			0
13	IS&R	L13	9	(("5422433") or ("5235131") or ("5218334") or ("5166772") or ("5089794") or ("4881770") or ("4678699") or ("4626963") or ("4451436")).PN.	USPAT	2003/07/0 10:59			0
14	BRS	L14	2	(chip or processor or microprocessor) and (emi same shield) and fan	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 11:00			0
15	BRS	L15	101	(chip or processor or microprocessor) and (emi same shield) and fan	USPAT	2003/07/0 11:06			0
16	IS&R	L16	5	(("6205026") or ("6061235") or ("5740013") or ("5473510") or ("5357404")).PN.	USPAT	2003/07/0 11:06			0
17	BRS	L17	1366	(chip or processor or microprocessor) and shield and fan	USPAT	2003/07/0 11:13			0
18	BRS	L18	1265	17 not 15	USPAT	2003/07/0 11:07			0
19	BRS	L19	119	18 and 361/$.ccls.	USPAT	2003/07/0 11:14			0
20	BRS	L20	116	19 not 6	USPAT	2003/07/0 11:07			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
21	L21	18	(chip or processor or microprocessor) and shield and fan	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 2 11:13			0
22	L22	188	18 and (heat adj sink)	USPAT	2003/07/0 2 11:15			0
23	L23	134	22 not 19	USPAT	2003/07/0 2 11:18			0
24	L24	32	((server or computer) same (thin or blade)) and fan	USPAT	2003/07/0 2 11:20			0
25	L25	27	((server or computer) same (thin or blade)) and cooling	USPAT	2003/07/0 2 11:21			0
26	L26	1652	((server or computer) same (thin or blade)) and cooling	USPAT	2003/07/0 2 11:26			0
27	L27	354	26 and fan	USPAT	2003/07/0 2 11:23			0
28	L28	6	(("0860874") or ("5419679") or ("5297005") or ("5132780") or ("4327398") or ("1884094")).PN.	USPAT	2003/07/0 2 11:24			0
29	L29	130	((server or computer) same (thin or blade)) and cooling	EPO; JPO; DERWENT; IBM_TDB	2003/07/0 2 11:28			0
30	L30	485	((server) same (thin or blade))	USPAT	2003/07/0 2 11:30			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
31	BRS	L31	45	((server) same (blade))	USPA T	2003/07/0 2 11:29			0
32	BRS	L32	27	30 and cooling	USPA T	2003/07/0 2 11:31			0
33	IS&R	L33	650	(361/687).CCLS.	USPA T	2003/07/0 2 11:31			0
34	BRS	L35	593	33 not 27	USPA T	2003/07/0 2 11:31			0
35	BRS	L36	593	35 not 31	USPA T	2003/07/0 2 11:39			0
36	BRS	L37	0	computer and (fan same noise same dumper$1)	USPA T	2003/07/0 2 11:40			0
37	BRS	L38	0	computer and (fan same noise same dumper$1)	EPO; JPO; DERW ENT; IBM_ TDB	2003/07/0 2 11:40			0
38	BRS	L39	0	computer and (fan same dumper$1)	EPO; JPO; DERW ENT; IBM_ TDB	2003/07/0 2 11:40			0
39	BRS	L40	1	computer and (fan same dumper$1)	USPA T	2003/07/0 2 11:42			0
40	BRS	L41	433	computer and (fan same damper$1)	USPA T	2003/07/0 2 11:42			0
41	BRS	L42	120	computer and (fan same cooling same damper$1)	USPA T	2003/07/0 2 11:44			0
42	BRS	L43	404	computer and (fan same cooling same noise)	USPA T	2003/07/0 2 11:56			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
43 IS&R	L44	4	(("9007233") or ("6512673") or ("6061237") or ("5864464")).PN.	USPAT	2003/07/02 11:57			0
44 IS&R	L45	15	(("9007233") or ("9006197") or ("6088224") or ("5969941") or ("5902276") or ("5788566") or ("5647713") or ("5316423") or ("5208730") or ("5186605") or ("4807718") or ("4568243") or ("4460534") or ("4286642") or ("4222304") or ("3319918") or ("3238835")).PN.	USPAT	2003/07/02 12:00			0
45 IS&R	L46	10	(("5999365") or ("5991163") or ("5912799") or ("5737194") or ("5734561") or ("5704117") or ("5483423") or ("5294748") or ("5193050") or ("5049701")).PN.	USPAT	2003/07/02 12:01			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
BRS	L47	548	hole$1 same emi	USPA 2	2003/07/0 12:41			0
BRS	L48	3	computer same fan same (smart adj card)	USPA 2	2003/07/0 12:45			0
BRS	L49	9	computer same fan and (smart adj card)	USPA 2	2003/07/0 12:46			0
BRS	L50	1094	server and (smart adj card)	USPA 2	2003/07/0 12:46			0
BRS	L51	0	(server same blade) and (smart adj card)	USPA 2	2003/07/0 12:48			0
BRS	L52	16	50 and fan	USPA 2	2003/07/0 12:49			0
BRS	L53	9	cooling same (smart adj card)	USPA 2	2003/07/0 12:48			0
BRS	L54	5	50 and 361/$.ccls.	USPA 2	2003/07/0 12:51			0